

TrakPro™ v5 Data Analysis Software



USB Quick Start Guide

This guide will help you to quickly begin using your TrakPro™ Data Analysis software for first time use with a personal computer and TSI® Equipment.

1. Software Installation

Download TrakPro™ v5 software from the TSI.com website in the [Service/Support](#) page. Once downloaded onto your PC, click the application file to begin installation. Follow the on-screen instructions to install the software.

2. Initial Start-Up of your TSI® Equipment

Plug the instrument into an AC power source or install the batteries. Press the **On/Off** button to turn the instrument on.



3. Communications Setup

After the instrument has completed its initial warm up, connect the USB cable from the instrument to your computer.

The “USB-A” connection to the computer, the “USB-B” or “USB mini-B” connection to the instrument.

4. Verify Communications

To verify successful Instrument-to-Computer communications:

Start the TrakPro™ software by double-clicking on the icon on the desktop.

For TrakPro™ v5 software (AM520 and AM520i only):

- Click on the **Devices** tab located on the left side of the application window. Verify that the Instrument and Serial Number information appear.

4. Verify Communications *(continued)*

For TrakPro™ v4.7.x software (all other TSI® products):

- Go to **Options | Software Configure...** menu. Choose the appropriate instrument for which you are connecting.
- Go to **Instrument Setup | Communications** menu. Verify that the Instrument and Serial Number information appear.

NOTICE

If the Instrument Model and Serial Number are not displayed, check driver installation by following the steps in the “TrakPro Data Analysis Software Installation Guide.”

Further Learning

You are now ready to learn about the daily operations of your TSI® Instrument and the TrakPro™ software. Refer to the Operation and Service manual for your equipment and the TrakPro™ Data Analysis Software manual for detailed instructions on how to use the various functions of instrument and software.



Knowledge Beyond Measure.

TSI Incorporated – Visit our website www.tsi.com for more information.

USA	Tel: +1 800 680 1220	India	Tel: +91 80 67877200
UK	Tel: +44 149 4 459200	China	Tel: +86 10 8219 7688
France	Tel: +33 1 41 19 21 99	Singapore	Tel: +65 6595 6388
Germany	Tel: +49 241 523030		

P/N 6006952 Rev C

©2022 TSI Incorporated

Printed in U.S.A.



NEED HELP?

SCAN OR CLICK HERE
TO CONTACT US



Air-Met Scientific
www.airmet.com.au