What your Tango™TX1 is telling you and what you should do about it.

♥»), ↓57EL 7WA OR-OR Err![!

tell you that your unit is In a

What your Tango is telling you and what you should do about it



The detected gas concentration exceeds the unit's low-alarm set point.

Gas Warning:

Respond according to company safety policy.

V (0) H25 TUR TWA alarm event

The cumulative gas readings have reached the unit's setting for the timeweighted average (TWA) exposure limit.

Leave the area

Respond according to company safety policy.



The detected gas concentration exceeds the unit's high-alarm set point.

Leave the area

Respond according to company safety policy.



The cumulative gas readings have reached the unit's setting for short-term exposure limit (STEL).

Leave the area

Respond according to company safety policy.



The detected gas concentration is outside of the sensor's measuring range.

Leave the area

Respond according to company safety policy.



From the time of initial display, there are fewer than 96 hours of remaining battery life.

Power warning:

Respond according to company safety policy.



NONGAS EVENTS

Due to insufficient battery power, the instrument is not operational.

Leave the area

Do not use the unit See your supervisor.



Dead battery

A critical hardware or system fault has occurred (483 shown).

Leave the area

Do not use the instrument (unit). See your supervisor.





Getting to know your TANG



give you important information about your unit's **Status**

What your Tango is telling you and what you should do about it



No faults

The instrument (unit) has no faults and needs no service Both sensors are functional and the unit is operating on DualSense® Technology.

Use it



The unit has no faults, needs no service, and has only one sensor installed. It can be used as a single-sensor instrument.

Use alert:

Respond according to company safety policy.



The unit has no faults. Sensor 1 has a failure; sensor 2 is functional. The unit can be used as a single-sensor instrument.

Use alert:

Respond according to company safety policy.



tell you that your unit is in need of **SERVICE**

What your Tango is telling you and what you should do about it



The unit is requesting a bump test.

Dock it*



The unit is requesting a calibration.

Dock it*



Sensor 2 has failed zero.

Dock it*

If the message persists, see your supervisor.



Sensor 2 has failed bump test and is requesting a calibration. Dock it*



Sensor 2 has failed calibration.

Dock it*

If the message persists, see your supervisor.

*When an instrument is docked, the docking stations will automatically perform scheduled tasks. When needed, tasks may be completed by qualified personnel who can operate the docking staton or perform them manually.



Single sensor calibration failure

SE 2

AMERICAS

Phone: +1-412-788-4353 Fax: +1-412-788-8353

ASIA PACIFIC Phone: +65-6561-7377 Fax: +65-6561-7787

info@ap.indsci.com

EMEA Phone: +33 (0)1 57 32 92 61 Fax: +33 (0)1 57 32 92 67 info@eu.indsci.com

www.indsci.com

1-800-DETECTS (338-3287) North America